

FY19 AVR**AVR-S640H**

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-S640H E3	0012	0202109031337 (A46Dh)	00.06	16.01 (0x0AC8)				76.04 (0x0031D782)		03110008 (0x63FE)	04100005 (0x8985)	5A711E54	2.1.620	U26.1 InfoVersion:4100-3073-8026-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.

AVR-S740H/X1500H

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-S740H E3	0015	0202109031344 (F652h)	00.06	17.17 (0x11E2)				75.03 (0x0031B33E)		05110008 (0x3458)	06100005 (0x8987)	5A711E90	2.1.620	U26.1 InfoVersion:3700-3044-8026-1000	3 : This update improves overall performance and stability.
AVR-X1500H E3	0015	0202109031344 (F652h)	00.06	17.17 (0x11E2)				75.03 (0x0031B33E)		05110008 (0x3458)	06100005 (0x8987)	5A711F1A	2.1.620	U26.1 InfoVersion:3700-3044-8026-1000	3 : This update improves overall performance and stability.
AVR-X1500H E2	0015	0202109031352 (4EC0h)	00.06	17.17 (0x11E2)				75.03 (0x0031B33E)		05120011 (0E88h)	06100005 (0x8987)	5A711EE8	2.1.620	U26.1 InfoVersion:3700-3025-1026-1000	3 : This update improves overall performance and stability.
AVR-X1500H JP	0015	0202109031358 (2F6Eh)	00.06	17.17 (0x11E2)				75.03 (0x0031B33E)		05140010 (8AEeh)	06100005 (0x8987)	5A711F54	2.1.620	U26.1 InfoVersion:3700-3085-0026-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.

AVR-S940H/X2500H

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-S940H E3	0015	0202109031433 (1815h)	00.06	17.17 (0x11E2)				78.01 (0x0031CBF5)		07100007 (B64Ah)	08100005 (0xFAF8)		2.1.620	U26.1 InfoVersion:1700-3033-7026-1000	3 : This update improves overall performance and stability.
AVR-X2500H E3/E2/JP	0015	0202109031433 (1815h)	00.06	17.17 (0x11E2)				78.01 (0x0031CBF5)		07100007 (B64Ah)	08100005 (0xFAF8)		2.1.620	U26.1 InfoVersion:1700-3033-7026-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.

AVR-X3500H

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-X3500H E3/E2	0014	0202109031449 (13BCh)	00.06	18.17 (0x1185)				80.02 (0x00310C3A)	82.01 (0x00314409)	09100008 (5E79h)			2.1.620	U26.1 InfoVersion:2700-3094-8126-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.

AVR-X4500H

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-X4500H E3/E2/JP	0013	0202109031506 (31FFh)	00.06	20.14 (0xE305)	21.16 (0x26DD)	22.11 (0x1CB3)	23.10 (0xAD1D)	84.02 (0x003126CA)	87.01 (0x00312826)	10100011 (0xB8C7)			2.1.620	U26.1 InfoVersion:2461-3060-1126-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.

AVR-X6500H

Model/SKU, Apply	PKG	Main(/Sub)	Main FBL	DSP	DSP2	DSP3	DSP4	Audio PLD	Video PLD	GUI Flash	PTMG	HTMG	LE60 Module	Remarks	Update Message
AVR-X6500H E3	0013	0202109031515 (FF9Dh)	00.06	20.14 (0xE305)	21.16 (0x26DD)	22.11 (0x1CB3)	23.10 (0xAD1D)	85.01 (0x002F57DD)	88.01 (0x003129A1)	11100011 (0x3BC4)			2.1.620	U26.1 InfoVersion:1461-3051-1126-1000	3 : This update improves overall performance and stability.
AVC-X6500H E2/JP	0013	0202109031515 (FF9Dh)	00.06	20.14 (0xE305)	21.16 (0x26DD)	22.11 (0x1CB3)	23.10 (0xAD1D)	85.01 (0x002F57DD)	88.01 (0x003129A1)	11100011 (0x3BC4)			2.1.620	U26.1 InfoVersion:1461-3051-1126-1000	3 : This update improves overall performance and stability.

*PKG number will not update at version display mode.